

Plate 1: View east to the hill crest.



Plate 2: View west along a steep slope, vegetated with regrowth Spotted Gum.



Plate 3: View east along a steep slope showing high levels of erosion.




Plate 4: View from the hill crest to south west over Lake Liddell.



Plate 5: View of an area of previous rehabilitation works that have exacerbated erosion.




Plate 6: View of an area of previous rehabilitation works within the Proposed Disturbance Boundary.




Plate 7: View of high levels of erosion along the slopes.




Plate 8: View of disturbance in the southernmost portion of the Proposed Disturbance Area.