

**AIRLY COAL PTY LTD - Lic. No. 12374 – Issued 22<sup>nd</sup> June 2005**

**2014**

Licence number: 12374  
 Annual Return Start: 12 Dec 2013  
 Annual Return End: 11 Dec 2014  
 Date Received: 30 Jan 2015

<u>Licence Condition number</u>	<u>Type of non-compliance</u>	<u>EPA actions</u>	<u>No. of times occurred</u>
L2.4	Exceedance of total suspended solids from Licence Discharge Point 8 after a rainfall event.	EPA to monitor future compliance with this condition	1

**2013**

Licence number: 12374  
 Annual Return Start: 12 Dec 2012  
 Annual Return End: 11 Dec 2013  
 Date Received: 06 Feb 2014

<u>Licence Condition number</u>	<u>Type of non-compliance</u>	<u>EPA actions</u>	<u>No. of times occurred</u>
L2.4	Discharge of water with high TSS from LDP3 caused by surface runoff from rain event. Surface runoff from a rain event caused the Train Loader Dam to discharge water through LDP3 with a level of TSS solids higher than the EPL limit.	EPA has written to licensee regarding non-compliance and relevant action	1

**2012**

<u>Licence Condition number</u>	<u>Type of non-compliance</u>	<u>EPA actions</u>	<u>No. of times occurred</u>
L2.1/L2.4	Exceed L2.1/L2.4 concentration limit for pH S.58 (x1, minor) - EPA has varied EPL (i.e the pH range) after taking into account background water quality in receiving waters.	change/amend licence conditions(s)	1
M2.2	Non compliance with M2.2 as one water sample not collected during discharge event (conductivity). EPA to monitor future compliance against condition.	Appropriate Action taken by licensee	1

**2011 – None**

**2010**

Licence number: 12374  
 Annual Return Start: 12 Dec 2009  
 Annual Return End: 11 Dec 2010

Date Received: 10 Feb 2011

<u>Licence Condition Number</u>	<u>Type of non-compliance</u>	<u>Nb. of incidents</u>
---------------------------------	-------------------------------	-------------------------

02.1	One dust deposition gauge in dust gauge network not meeting requirements of AS/NZS3580 due to veg regrowth around gauge.	1
------	--	---

### Summary of Licence No: 12374

[View this licence](#) (PDF document 200 kb)

**Licence holder:**

**Premises:**

**AIRLY COAL PTY LIMITED**  
AIRLY COAL PROJECT  
GLEN DAVIS ROAD CAPERTEE 2846

**LGA:** City of Lithgow **Catchment:**  
Hawkesbury  
\$4,750.00

**Administrative fee:**

**Status of licence:**

**Licence type:**

**Activity type:**

Issued  
Premises  
Coal Mining

**Applications**

<u>Number</u>	<u>Application type</u>	<u>Current status</u>	<u>Date</u>
12374	<a href="#">View application</a> New Licence	Approved	22 Jun 05

**Annual Return Information** information about non-compliance

<u>Start date</u>	<u>End date</u>	<u>Date received</u>	<u>Non-compliance</u>	<u>LBL Data</u>
12 Dec 05	11 Dec 06	28 Dec 06	No	Not subject to LBL

Section 55 Protection of the Environment Operations Act 1997

## Environment Protection Licence

Licence - 12374

Environment Protection Authority - NSW Page 1 of 18

Archived: 06-Oct-2006

**Licence Details**

Number: 12374

Anniversary Date: 12-December

Review Due Date: 12-Dec-2008

**Licencee**

AIRLY COAL PTY LIMITED, LEVEL 18 BT TOWER, 1 MARKET STREET, SYDNEY NSW 2000

**Licence Type** - Premises

**Premises** - AIRLY COAL PROJECT, GLEN DAVIS ROAD, CAPERTEE NSW 2846

**Scheduled Activity** - Coal Mines

**MINING LEASE NO. 1331**

**Fee Based Activity Scale** - Coal Mining (26) 0 - 500000 T produced

**Region**

North West – Bathurst, 219 Howick Street, PO Box 1388 BATHURSTNSW 2795

Phone: 02 6332 7600 Fax: 02 6332 2387