

Bunbury Curran H:11

LANDSLIDES ON CENTRAL HILLS' SLOPES, CAMPBELITOWN.

See photo 12, p.33.

.5.1982.





Bunbury Curran Hill as viewed from St Andrews Road, Varroville (portion of the grant to The hillside is unstable, with evidence of slip, slump and creep. Photographs by 20 May 2000.





Bunbury Curran Hill as viewed from St Andrews Road, Varroville (portion of the grant to The hillside is unstable, with evidence of slip, slump and creep. Photographs by 20 May 2000.