



SITE INSPECTION NOTES

This meeting is part of the determination process

Project	Narrabri Gas Project (SSD-6456)
Meeting Location	Narrabri and surrounds - as per inspection map included as Attachment A
Date	6 July 2020
Time	8.00am – 5.00pm

ATTENDANCE

Commission Members	Mr Stephen O'Connor Mr John Hann Prof. Snow Barlow	Panel Chair
Office of IPC	Casey Joshua Troy Deighton Kym Statham Richard Beasley	Principal Case Manager Principal Public Affairs Officer Senior Events Manager Counsel Assisting
Applicant	Tracey Winters Nick Fox Todd Dunn Josh Gilroy Andrew Snars Rob Simpson Marty Sullivan Dr Richard Cresswell	Santos – Strategic Adviser External Affairs Santos – Head of Environment and Access Santos – Project Manager Narrabri Santos – Social and Environmental Studies Coordinator Santos – Regional Manager Santos – Vice President EcoLogical Australia – Lead Terrestrial Ecology EcoLogical Australia – Lead Groundwater and Surface Water
Community Representatives	Margaret Fleck Tony Pickard Edward Trindall Cara Stoltenberg	North West Alliance Artesian Bore Water Users Association Narrabri Local Aboriginal Land Council Narrabri Shire Council
Invited, but not available on the day	Jon-Maree Baker	Namoi Water



LOCATIONS AND KEY OBSERVATIONS (photos included as **Attachment B**)

Part 1:

1. Narrabri Operations Centre

- Welcome to Country provided by Edward Trindall
- Opening Statement and Introductions
- Safety induction and overview of the Site Inspection

2. Bibblewindi Facility

- Travel between the Narrabri Operations Centre and the Bibblewindi Facility – the Panel observed the intersection of the Newell Highway and the X-line Road, proposed for upgrade.
- The Panel observed the compressor station, decompression ponds, the flare infrastructure, the lease pad and the sterile zone.
- Rehabilitation site – the Panel observed the rehabilitation to date from the Eastern Star Gas spill.

3. Bibblewindi 24/25

- The Panel observed the flowline infrastructure for two appraisal wells.

4. Bohena 2 rehabilitation area

- The Panel observed the Eastern Star Gas spill site that is being rehabilitated.

5. Leewood water storage and reverse osmosis treatment facility

- The Panel observed brine and produced water storage ponds and the pond barrier lining.
- The Panel were also shown the Reverse Osmosis plant.

6. Bohena Creek discharge location

- The Panel inspected the Bohena Creek discharge location, which is the site for a managed release of produced water.

7. Tintsfield

- The Panel observed a well site on private property.

8. Wilga Power Station

- The Panel inspected the Wilga Park Power Station, where the gas is converted into electricity and is being fed into the National Electricity Main.

Conclusion of Day 1 of the Site Visit

Part 2:

On Tuesday, 7 July 2020 the Panel attended sites 9 and 10 with representatives from Narrabri Shire Council. **Attendees from Narrabri Shire Council** include:

- Cathy Redding (Mayor)
- Cameron Staines (Deputy Mayor)
- Daniel Boyce (Executive Manager Planning and Environment)



9. Narrabri Industrial site

- The Panel inspected the site for the Narrabri Industrial park ('Northern NSW Inland Port'), where the Industrial Park and Freight Logistics Port are planned.


10. Civeo Narrabri

- The Panel also visited the Civeo Facility in Narrabri – workers accommodation, 1 bedroom studios with ensuites.

Meeting notes taken by Casey Joshua

Attachment A: Site Inspection Map

Approx. location of 9



Locations

- Major Town

Infrastructure

- Existing Well
- Facility Location
- Power Station
- Water Flow Line - Existing
- Gas Flow Line - Existing

Transport

- Highway
- Sealed Road
- Unsealed Road

Tenures

- Santos Facilities
- Cadastral Parcels
- Travelling Stock Reserves
- Protected Areas
- State Forest

Tenements

- Santos Tenements

NGP

- Narrabri Gas Project Area

Santos
Energy New South Wales

Narrabri Gas Project Area

2 0 2 4 6 km

Date: February 2017 File No. Gunnedah 350b

GOA

Certain information in this map is provided under license from third parties and is subject to intellectual property rights. Santos has made every effort to ensure that information is accurate and up-to-date but does not guarantee or warrant the accuracy, completeness or currency of, and takes no responsibility for any error or omission relating to, this map. Santos and its related bodies corporate accept no responsibility for any errors or omissions. The "User" acknowledges that information and maps are in a constant state of change and accepts all limitations. To the maximum extent permitted by law, Santos and its related bodies corporate will not be liable for any cost, loss or damage arising out of the use of this map.



Attachment B: Site Inspection Photos

6 July 2020

Location 2



Location 3





SITE INSPECTION PHOTO'S

6 July 2020

Location 4



Location 5





SITE INSPECTION PHOTO'S

6 July 2020

Location 6



Location 7





SITE INSPECTION PHOTO'S

6 July 2020

Location 8



Location 9





SITE INSPECTION PHOTO'S

6 July 2020

Location 10

