



# SITE INSPECTION PHOTOS

10 November 2021

*Location 1 – Site Access*








# SITE INSPECTION PHOTOS

10 November 2021

*Location 2 – Location of proposed Noise Wall and existing Vehicle Wash Bay*



*Location 3 – Eastern Boundary*







# SITE INSPECTION PHOTOS

10 November 2021

*Location 4 – Processing Area with legacy construction waste*



*Location 5 - Melaleuca Bioconvexa Buffer Area*







# SITE INSPECTION PHOTOS

10 November 2021

*Location 6 – Stage 1 Area*

