



TABLE OF WINDOWS		
No.	TOP	BOTTOM
1	99.38	98.36
2	99.38	98.36
3	102.78	101.57
4	102.78	101.57
5	102.78	102.66
6	104.07	102.66
7	104.07	103.00
8	104.07	102.69
9	103.50	102.36
10	103.50	102.16
11	103.50	102.16
12	103.50	102.16
13	103.50	102.16
14	103.50	102.16
15	103.50	102.3
16	102.33	101.15
17	102.33	101.15
18	102.33	101.15
19	102.33	101.35
20	102.33	100.90
21	100.63	99.33
22	100.63	99.33
23	100.63	99.33
24	100.63	99.47
25	98.72	97.54
26	98.72	97.72
27	97.70	95.90
28	97.70	95.90
29	97.70	95.90
30	97.87	96.67
X	101.52	98.92
Y	99.64	97.26

NOTES:

- THIS SURVEY IS NOT A BOUNDARY SURVEY AND NO BOUNDARIES HAVE BEEN MARKED.
- THE RELATIONSHIP OF IMPROVEMENTS TO BOUNDARIES ARE DIAGRAMMATIC ONLY AND SHOULD BE CONFIRMED BY FURTHER SURVEY.
- BEARINGS, DISTANCES & AREAS ARE BY TITLE &/OR DEED ONLY.
- PLAN ORIENTATION BY DP 1213271 (MGA)
- ORIGIN OF DATUM WAS DERIVED FROM SSM 75318 HAVING R.L. 89.162 (A.H.D.).
- THIS DRAWING IS SUBJECT TO COPYRIGHT. IT MUST NOT BE REPRODUCED IN WHOLE OR PART WITHOUT PRIOR WRITTEN CONSENT OF NORTH WESTERN SURVEYS Pty Ltd.
- THE TITLE BLOCK AND THESE NOTES FORM AN INTEGRAL PART OF THIS PLAN AND SHOULD NOT BE REMOVED WITHOUT CONSENT OF NORTH WESTERN SURVEYS Pty Ltd.
- INFORMATION SHOWN HEREON IS ONLY CURRENT AT THE DATE OF SURVEY SHOWN.
- ANY CHANGES, MODIFICATIONS OR ALTERATIONS TO THE SITE AFTER THE DATE OF SURVEY IS NOT THE RESPONSIBILITY OF NORTH WESTERN SURVEYS Pty Ltd.
- ONLY VISIBLE SERVICES HAVE BEEN LOCATED AND CONFIRMATION OF THESE LOCATIONS SHOULD BE MADE WITH THE RELEVANT SERVICE AUTHORITY PRIOR TO ANY DEMOLITION, EXCAVATION OR CONSTRUCTION ON THE SITE.
- A DIAL-BEFORE-YOU-DIG SERVICES SEARCH (WWW.1100.COM.AU) SHOULD BE CARRIED OUT FOR THE POSSIBLE LOCATION OF ANY NON-VISIBLE SERVICES.
- ONLY VISIBLE ADJOINING WINDOW & RIDGE LEVELS HAVE BEEN LOCATED. FURTHER SURVEY IS REQUIRED TO COMPLETE ADJOINING WINDOWS.
- BOUNDARIES & CHARTING ON THIS SHEET ARE INDICATIVE FOR GROUND LEVEL ONLY.

- LEGEND:**
- BRICK SIGN
 - TAP
 - DRAINAGE PIT GRATED
 - DRAINAGE PIT CONCRETE
 - SEWER MANHOLE
 - TELSTRA PIT
 - SIGN
 - WATER METER
 - SEWER INSPECTION OPENING
 - HYDRANT
 - KERB INLET PIT
 - DRAINAGE PIT OTHER
 - BOTTOM OF BANK
 - TOP OF BANK
 - SEWER LINE APPROX. POSITION
 - AWNINGS
 - BALCONY
 - TOP OF KERB
 - VEHICLE CROSSING
 - LIGHT POLE
 - SUBSTATION
 - BITUMEN SURFACE
 - CONCRETE SURFACE
 - PAVER SURFACE



SITE AREA: 15,960 sqm

REV.	DESCRIPTION	DATE	APPR.	BAR SCALE	CLIENT/PROJECT	SURVEYED:	GRID:	DATUM:	TITLE	SHEET
				0 12 5 10 15 20 25 30 Scale 1:300	North Western Surveys Surveyors, Engineers & Water Servicing Coordinators 1/11 Romford Road, P.O. Box 1045, Blacktown N.S.W. 2148 Phone: 9831-2040 Fax: 9622-5716 Email: nws@nwsurveys.com.au	R.S	M.G.A.	A.H.D.	TOPOGRAPHIC SURVEY OVER LOT 1 IN DP 270106 AT No. 34 - 46 BROOKHOLLOW AVENUE, NORWEST, L.G.A. THE HILLS SHIRE	1
00	ORIGINAL ISSUE				THIS PLAN MUST NOT BE USED FOR CONSTRUCTION UNLESS SIGNED AND APPROVED BY PRINCIPAL CERTIFYING AUTHORITY	N.V	-	1:300	PROJECT MANAGER:	2
					THIS DRAWING IS SUBJECT TO COPYRIGHT. IT MUST NOT BE REPRODUCED IN WHOLE OR PART WITHOUT PRIOR WRITTEN CONSENT OF NORTH WESTERN SURVEYS Pty. Ltd.	DESIGNED:	DESIGN CHECK:	VERTICAL RATIO:	DATE:	OF SHEETS
						-	-	-	20/08/2018	00
									REVISION:	PROJECT REFERENCE:
									00	17234/001