




RECORD OF SITE INSPECTION

SITE INSPECTION NOTES		
Project:	Glebe Island Silos Signage	
Meeting Location:	Glebe, Ultimo, Pyrmont	
Date:	Thursday, 4 August 2022	
Time:	1.00pm – 3.30pm	
ATTENDEES		
Commissioners:	Richard Mackay Peter Williams	Chair
Office of the IPC:	Casey Joshua Jane Anderson	Principal Case Manager Senior Planning Officer
LOCATIONS AND KEY OBSERVATIONS		
<p>1) Jubilee Park to Glebe</p> <p>The Panel walked from Jubilee Park to Glebe to observe views to the Glebe Island Silos from the public walkway.</p> <p>2) Glebe to John Street Square</p> <p>The Panel caught the light rail from Glebe to John Street Square to view and access the site from the Pyrmont direction.</p> <p>3) Anzac Bridge</p> <p>The Panel walked from John Street Square over the Anzac Bridge and then back to Jubilee Park, observing the Glebe Island Silos at visible points from the public walkway.</p> <p>4) Night-time viewing</p> <p>The Panel independently viewed the silos at night to observe the lighting.</p> <p>Attachment A: Site Inspection Route (includes numbered locations for photographs in Attachment B)</p> <p>Attachment B: Site Inspection Photos (taken from numbered stops indicated on Attachment A)</p>		
Meeting closed at: 3.30pm		



RECORD OF SITE INSPECTION

ATTACHMENT A: Site Inspection Map, including photograph locations



ATTACHMENT B: Site Inspection Photographs

1



2



3



4



v1.1



5



6



7



8



9



v1.1