

RECORD OF NEIGHBOURING SITE VISITS

SITE INSPECTION NOTES		
Project:	Birriwa Solar Farm (SSD-29508870)	
Meeting Locations:	Birriwa, Merotherie and surrounding areas	
Date:	4 June 2024	
Time:	2:00pm	
ATTENDEES		
Commissioners:	Janett Milligan	Panel Chair
	Suellen Fitzgerald	Panel Member
	Duncan Marshall	Panel Member
Office of the IPC:	Kendall Clydsdale	Principal Case Manager
	Geoff Kwok	Senior Planning Officer

Various landowners and representatives at their respective sites

LOCATIONS AND KEY OBSERVATIONS

1) R47

- · Observed the site from R47 (vicinity of existing dwelling), looking east, south and south-east
- Landowners discussed their concerns of the project's potential impacts to their property, including potential
 impacts to agricultural operations.

2) R11

- . Observed the site from R11 (vicinity of existing dwelling), looking south, south-east and south-west
- Landowners discussed their concerns of the project's potential impacts to their property, including potential social and cumulative impacts.

3) R33

- Observed the site from the R33 frontage on Birriwa Bus Route North, looking west and south-west
- Landowners discussed their concerns of the project's potential cumulative impact with other proposed renewable projects in the area.

4) R5


- Observed the site from R5 (vicinity of existing dwelling), looking north and east
- Landowners discussed their concerns of the project's potential impacts to their property, including potential social, tourism and cumulative impacts.

Meetings closed at: 4:30pm



RECORD OF NEIGHBOURING SITE VISITS

MAP OF NEIGHBOURING SITES VISITED





RECORD OF NEIGHBOURING SITE VISITS

PHOTOS TAKEN FROM NEIGHBOURING SITES

Figure 1 – R47, looking east towards the site



Figure 3 – R33, looking south-west towards the site



Figure 2 – R30, looking south towards the site



Figure 4 - R5, looking north towards the site

